

Bridge Assessment Number 8

Bridge Name	Cottonwood Creek Road Bridge (also known as “Garden Creek” Bridge)
River	Upper Ruby
Bridge Location Description	First public bridge above Ruby Reservoir
Bridge Coordinates (Lat., Longitude)	N 45 deg. 11.554 min. W 112 deg. 8.548 min.
Accessibility Assessment (safe as is, safe with work, not safe)	<ul style="list-style-type: none"> • Adequate parking for 2 cars at NE corner (downstream, East); should be reviewed. • Barbed wire is connected to guard-rail at NE Corner, but gap between wires appears large enough to crawl through if one is careful. • NW corner affords access for one pedestrian through the gap by the guardrail. • SW corner has gate through which access is easily afforded. • SE corner offers no access—barbed wire is attached to guardrail.
Notes: (What would make it safe, why is it not safe as is, etc.)	Parking should be reviewed.
Name(s) of person conducting review	Dave Delisi
Date of review	4/30/09

Photos:







Bridge Assessment Number 9

Bridge Name	Sweetwater Road Bridge
River	Upper Ruby
Bridge Location Description	Second public bridge over the Ruby past the Ruby Reservoir when heading south.
Bridge Coordinates (Lat., Longitude)	N 45 deg. 09.108 min. W 112 deg. 8.854 min.
Accessibility Assessment (safe as is, safe with work, not safe)	<ul style="list-style-type: none"> • Parking for 1 car, perhaps two (should be reviewed) on road to NW of bridge. • Rip-rap may present challenge to some.
Notes: (What would make it safe, why is it not safe as is, etc.)	Access seems good at all four corners of the bridge.
Name(s) of person conducting review	Dave Delisi
Date of review	4/30/09

Photos:



Sweetwater, NW Corner



Sweetwater Bridge, SE Corner



Sweetwater, NE Corner



Sweetwater Bridge, SW Corner



Sweetwater Bridge SW Corner Looking East



Bridge Assessment Number 10

Bridge Name	Ledford Bridge
River	Upper Ruby
Bridge Location Description	Third public bridge over the Ruby past the Ruby Reservoir when heading south.
Bridge Coordinates (Lat., Longitude)	N 45 deg. 05.169 min. W 112 deg. 04.315 min.
Accessibility Assessment (safe as is, safe with work, not safe)	<ul style="list-style-type: none"> • Parking for 2 cars (should be reviewed) on road to SE of bridge • Access possible for some at NE and SE corners over wooden fence • Access possible for some at NW and SW corners through gap at guard rail
Notes: (What would make it safe, why is it not safe as is, etc.)	Access seems adequate at all four corners of the bridge, although It could be improved and should be reviewed
Name(s) of person conducting review	Dave Delisi
Date of review	4/30/09

Photos





Bridge Assessment Number 11

Bridge Name	Lower Vigilante Bridge, aka Warm Springs Bridge
River	Upper Ruby
Bridge Location Description	Fourth public bridge over the Ruby past the Ruby Reservoir when heading south.
Bridge Coordinates (Lat., Longitude)	N 45 deg. 01.807 min. W 111 deg. 58.438min.
Accessibility Assessment (safe as is, safe with work, not safe)	<ul style="list-style-type: none"> • Parking for 1-2 cars (should be reviewed) on road to SE of bridge • Access to river is possible by crossing fence at any of the 4 corners of this bridge
Notes: (What would make it safe, why is it not safe as is, etc.)	Access seems adequate at all four corners of the bridge, although Not everyone is capable of crawling over the fence; adding a stile of some sort would help.
Name(s) of person conducting review	Dave Delisi
Date of review	4/30/09

Photos



